

DELIVERY CONDITIONS MATERIAL

SHEET METAL/PROFILES AND OTHER GOODS

1. Sharp cutting, trimming and other edges of sheets/fittings should be deburred with a rounding radius of at least 0.5 mm. The same applies to profiles. This is necessary in order to obtain sufficient coverage of the coating on the edges and thus to provide the necessary protection.
2. Goods must be delivered without saw chips.

CONTAMINATION OF SUPPLIED MATERIAL

3. Products must be delivered clean and free of rust. Gerritsen van Groningen B.V. can remove this upon request, provided that this has been communicated beforehand.
4. Make sure that the material is free from (excessive) contamination such as oil, grease, lacquer, welding spray and silicones. These substances can affect the quality of the paintwork.
5. Markings on products, such as printing, adhesive tape, or stickers, should be removed beforehand. There is a risk (particularly with light colours) that printed letters/numbers will show through the coating. In the case of adhesive tape, glue residues can produce an unsightly result. Do not use permanent markers on the material to be treated either.

PRODUCT DESIGN

6. If possible, make sure there are enough suspension points in the products. If in doubt, contact us so that no unnecessary holes are made in your product.
7. Before we refinish products that have already been coated, we always consult with you first. Together, we discuss your wishes and look at the possibilities.

ORDER SPECIFICATION

8. In order to ensure that your order progresses smoothly, we would like to receive a written confirmation by e-mail. Your order confirmation must state the order, quotation, colour number and desired delivery time. You can also let us know your specific wishes (masking, capping, suspension points, etc.)
9. Based on our quality protocol, we naturally carry out an entrance check on materials. Here, we look especially at the overall condition of the products. If we find

any damage, we will contact you immediately to discuss the desired follow-up. As the client, you are responsible at all times for the products supplied.

10. In your application or order, clearly indicate the material involved (e.g. aluminium, steel, cast iron or galvanised steel). Galvanised steel must meet the VISEM quality requirements.

PACKAGING

11. The goods must be delivered, protected, on pallets, transport containers or packages. The containers/packages/pallets are labelled with the full details of the products. The delivery of products is accompanied by a delivery note that states matters such as: sender, article (numbers), length and number.
12. If there are specific packing or masking instructions, these must be known to us prior to the order.